


EXPLANATION

- Corrective Action Monitoring groundwater well
- Detection Monitoring groundwater well
- Piezometer
- ▲ Surface water monitoring location
- Private agricultural well
- ⊗ Vadoses zone/gas monitoring probe
- ⊗ Monthly methane gas inspection location
- ▨ Approximate fill area January 1, 2006 to March 31, 2006
- ▨ Approximate fill area April 1, 2006 to June 30, 2006

Dimscale: 1 Ltscale: 1 Pstlscale: 1=2
 G:\063-7096\FIGURES\MONITORING LOCATIONS.DWG 7/29/06



DATE	7/29/06
DWN	KMM
APP	TLV
REV	0
PROJECT NO.	063-7096

FIGURE 2
 CITY OF SANTA MARIA
 SANTA MARIA LANDFILL
 SANTA BARBARA COUNTY, CALIFORNIA
MONITORING LOCATIONS